

编软件功能列表

	工具组	图标	工具清单	1D/2D 读码	测量/引导标准版	全功能版
1	图片		相机控制	√	√	√
			截取图片	√	√	√
			读取	√	√	√
			保存图片	√	√	√
2	校准		定位	√	√	√
			畸变		√	√
			映射		√	√
3	控制		线程控制	√	√	√
			变量访问	√	√	√
			AND/OR	√	√	√
			阵列变量	√	√	√
			CCS 控制	√	√	√
			图表	√	√	√
			评估	√	√	√
			图像信息	√	√	√
			字串分类	√	√	√
			秒表	√	√	√
			字串表格	√	√	√
			子程序	√	√	√
			表格	√	√	√
4	通讯		设置输出	√	√	√
			读取输入	√	√	√
			自由口	√	√	√
			脚本	√	√	√
			字串控制	√	√	√
			控制语句发送	√	√	√
			In文本	√	√	√
			MC 通讯	√	√	√
			ModBus 口	√	√	√
			文本	√	√	√